

A L≣G≣⊓C≣ Company

COOK COUNTY PUBLIC SCHOOLS

FACILITY ASSESSMENT SUMMARY

Board Work Session November 2, 2023

AGENDA

- Review basics of the Districts facilities/site
- How are budgets developed
- Review of facility needs / budgets
- Overall Budget Summary
- Utility Summary
- Next Steps



School Site


~**51** Acres



Adjacent Land (North of School) ~**20** Acres



A **40** Acre site 12 miles up the shore



The Data from MDE spreadsheet seems incorrect?

Measurements from existing plans indicate ~130,000 SF

Plus, an additional 10,000 SF for the bus garage and shop

Corrections to MDE by 12/15/23

How are budgets developed

- Not estimates
- Not bids
- Based on the team's project history of recently bid projects of similar scope
 - Typically, utilizing the average of the bids. Low bid creates risk of contractor not having all items included or "buying" the job to keep work.
- Utilize industry standard databases
- Budgets are inclusive of:
 - Contractor costs
 - Inflation (7%)
 - Contingency (5%)
 - Testing/Survey/Commissioning/Permitting, etc.
 - Fees

COOK COUNTY SCHOOL BUILDING ENVELOPE

Window Replacement

EXISTING

Science room windows were replaced in 2018. Majority of remaining windows are from 1998 and approaching end of life expectancy. Replacement parts are getting hard to find.

PROPOSED

Replace all windows. Could also phase replacement over several years

BUDGET

\$507,000





COOK COUNTY SCHOOL BUILDING ENVELOPE

Exterior Door Replacement

EXISTING

Majority of exterior doors are original from 1998. Issues with rusting and not closing properly.

PROPOSED

Replace doors and update door hardware and electronics as needed.

BUDGET

\$238,800





COOK COUNTY SCHOOL BUILDING ENVELOPE

Tuckpointing, Caulking & Repairs

EXISTING

Majority of the facility is in fair/good condition.
Spot repairs needed.
Survey conducted by ARI (Widseth). Waiting on results.

PROPOSED

Conduct repairs per report recommendations

BUDGET

\$ (tbd)



COOK COUNTY SCHOOL ROOF SYSTEMS

Roof Replacements

EXISTING

District has done a good job on keeping up on roof replacements. Ponding an issue in few locations. Remove debris periodically. No roof sections are due for replacement at this time.

PROPOSED

No work proposed at this time

BUDGET

\$0





COOK COUNTY SCHOOL INTERIOR SURFACES

Flooring Upgrades – Carpet, Hall VCT & Gyms

EXISTING

Old carpet beyond life expectancy Defective product – Hallway VCT Main Gym & YMCA Gym

PROPOSED

Replace older carpet with carpet squares.

Remove and replace defective Hallway flooring Sand/Refinish Main & YMCA gyms

BUDGET

\$114,000 – Carpet \$249,700 – Hallway \$59,000 – Main Gym \$43,100 – YMCA Gym



COOK COUNTY SCHOOL MECHANICAL SYSTEMS

Rooftop Equipment Replacement

EXISTING

At or Beyond life expectancy R-22 Refrigerant

PROPOSED

Replace Auditorium condensing unit and coil Replace RTU's

BUDGET


\$173,900 – 1998 Units \$154,100 – 2008 Units

1998 Units

- RTU-1 (Aud. Control Rm.)
- RTU-2 (Rm. 117 & 424)
- ACCU-1 (Aud. Cond. Unit)

2008 Units

- RTU-4 (IT/Server Rm.)
- RTU-5 (Rm. 299/300)
- RTU-7 (Board Room)





COOK COUNTY SCHOOL MECHANICAL SYSTEMS

Domestic HW Heater Replacements

EXISTING

2 Units are from 2007 and are at or beyond life expectancy

PROPOSED

Replace units with High Efficiency Units

BUDGET

\$49,300





COOK COUNTY SCHOOL MECHANICAL SYSTEMS

Control System Upgrades


EXISTING

System is operating properly, but there are some System and component upgrades available to enhance performance

PROPOSED

Consider all or partial upgrades

BUDGET Up to \$85,000



• Improved functionality

Remote access via Smart Phone



COOK COUNTY SCHOOL MECHANICAL SYSTEMS

Dehumidification

EXISTING

Only a few areas have cooling or dehumidification.


PROPOSED

Upgrade existing ventilation systems to provide dehumidification

BUDGET Up to \$3M+ pending final scope

The ventilation systems installed with the 1998 addition and the units installed in 2008 were designed for "potential" future cooling.

- The air handlers have a space for cooling coil
- · The ductwork that was installed is insulated





COOK COUNTY SCHOOL ELECTRICAL SYSTEMS

LED Lighting

EXISTING

Majority of the facility lighting is 1998 fixtures with T8 fluorescent lamps

PROPOSED

Upgrade to LED fixtures. Interior and exterior walls and entry canopies. Energy code requirements.

BUDGET \$1,255,000



COOK COUNTY SCHOOL ELECTRICAL SYSTEMS

PA / Bell / Clock Systems

EXISTING

The PA/Bell and clock systems are outdated and should be upgraded Outdated Camera's

PROPOSED

Upgrade systems

BUDGET

\$47,900 - Clocks only \$20,500 - PA Head End

\$178,000 - Completely new system

\$164,400 – Security Cameras (~100)



COOK COUNTY SCHOOL SITE PROJECTS

Parking Lots and Drives

EXISTING

Very recent repairs, patching, sealing and striping. Bus loop is getting close to the need for full replacement.

PROPOSED

Replace back drive and bus loop. Replace path around Performing Arts. Spot concrete repairs.

BUDGET

\$591,700 – Bus loop/drive \$23,000 – path \$10,000 – Concrete (allotment)





COOK COUNTY SCHOOL SITE PROJECTS

Playgrounds

EXISTING

Wood chips (ADA concern)
Paved basket / play area need repairs.

PROPOSED

Replace wood ships with ADA compliant Engineered wood chips.

Patch and seal play area.

BUDGET

\$98,600 – Wood Chips \$6,500 – Play area patch/seal and paint





COOK COUNTY SCHOOL SITE PROJECTS

Accessibility

EXISTING

Accessibility to playground Accessibility to bleachers


PROPOSED

Install paths to bleachers. Replace Door #9 entry steps and add ramp.

BUDGET

\$45,600 – Paths \$130,800 – Door #9 ADA





condition. Replace entry with ADA ramping and add push button door system.

Add paved paths to Home and Visitor bleachers.

COOK COUNTY SCHOOL SITE PROJECTS

Athletic Field

EXISTING

Irrigation is provided by a hose from a fire hydrant at the opposite end of the property (leaks occur).

Fencing around the field is old and damaged.

Field lighting is original (some lamps are burned out)

PROPOSED

Install LED fixtures Replace fence

BUDGET

\$123,300 – Replace Fence \$143,800 – LED lighting & Wire upgrade \$ (tbd) - Irrigation



COOK COUNTY SCHOOL Performing Arts

Misc. Upgrades

EXISTING

Several areas sited by staff for improvement


PROPOSED

Lighting and Lightboard upgrades Dropdown screen Skydeck System

BUDGET

\$84,200 – Misc. upgrades \$532,500 – Skydeck System





- LED Stage Lighting (10)
- · Light Board
- Drop Down Screen ~(20'W x 11'H)
- Source Four LED conversion kits (20)
- Catwalk (Skydeck System)





COOK COUNTY SCHOOL Locker Rooms

Remodeling

EXISTING

Outdated Locker Rooms

PROPOSED

Remodel and update locker rooms. Provide individual showers.

BUDGET

\$tbd





COOK COUNTY SCHOOL Bus Garage / Shop

Upgrades

EXISTING

Shop facility is over 50 years old and outdated

Majority of the lot is dirt

PROPOSED

Replace Shop Building Pave rest of parking area

BUDGET

\$119,600 - Pave rest of lot (\$tbd) - New Shop Building







Budget Summary

Mech. / Ventilation / IAQ Upgrades	Budget
Replace R-22 Cond. Unit/Coil for Performing Arts	\$71,200
Replace R-22 Roof Top Units (2 - 1998 units)	\$102,700
Replace R-22 Roof Top Units (3 - 2008 units)	\$154,100
Replace 2 - 2007 Domestic Hot Water Heaters	\$49,300
Dehumidification	\$2,993,000
Control System Upgrades	\$90,400
	\$3,460,700
Electrical / LED Lighting	
Upgrade Lighting to LED (interior & exterior walls)	\$1,255,000
New Clocks only	\$47,900
New PA Head End	\$20,500
New PA/Bell & Clock System	\$178,000
New Security Cameras (100)	\$164,400
Football Field LED fixtures/wiring	\$143,800
	\$1,809,600

Building Envelope Upgrades	Budget
Window Replacements	\$0
Priority 1	\$184,900
Priority 2	\$148,400
Priority 3	\$173,700
Replace Orig. Exterior Doors (1998)	\$238,800
Tuckpointing (ARI report)	\$0
	\$745,800
Parking Lots & Sidewalks	
ADA sidewalks/paths to Home/Visitor bleachers	\$45,600
ADA ramp/stairs at door #9	\$130,800
Pave rest of Bus Garage lot	\$119,600
Replace bus loop and drive	\$591,700
Replace path around Performing Arts	\$23,000
Patch/Seal/Sealcoat Play area	\$6,500
	\$917,200



Budget Summary

Interior Finishes	Budget
Older Carpet Replacements	\$114,000
Hallway Tile Replacement	\$249,700
Main Gym - Sand/Refinish/Lines	\$59,000
YMCA Gym - Sand/Refinish/Lines	\$43,100
	\$465,800
Other	
Replace Football Field Fencing	\$123,300
Playground ADA Engineered Wood Chips	\$98,600
Performing Arts (Skydeck system)	\$532,500
Performing Arts (Misc. upgrades)	\$84,200
Irrigation System (TBD)	\$0
Track (TBD)	\$0
New Bus Maintenance Shop (TBD)	\$0
	\$838,600

Category	Budget
Mech. / Ventilation / IAQ Upgrades	\$3,460,700
meem / remailed / may oppliates	ψο, 100,700
Electrical / LED Lighting	\$1,809,600
Building Envelope Upgrades	\$745,800
	. ,
Parking Lots & Sidewalks	\$917,200
Interior Finishes	\$465,800
Other	\$838,600

GRAND TOTAL \$8,237,700



ISD#166 - PRELIMINARY BIM SUMMARY - DRAFT Project Selection Worksheet Potential Funding Mechanism											
Selected	Project Selection Worksheet	Estimated Budget	Capital	oter Safety	Safe El	LTFM	ase Levy B	atementa	avings a	ESSER 3	"Selected Only" Estimated Budge
ď.	Building Improvement Measure (BIM) Description		Ľ	Ι.,	(7)		Fe	β	3	В	
0	OK COUNTY SCHOOLS										
	Mech. / Ventilation / IAQ Upgrades										
х	Replace R-22 Cond. Unit/Coil for Performing Arts	\$71,200				х					\$71,200
х	Replace R-22 Roof Top Units (2 - 1998 units)	\$102,700				х					\$102,700
x	Replace R-22 Roof Top Units (3 - 2008 units)	\$154,100				х					\$154,100
х	Replace 2 - 2007 Domestic Hot Water Heaters	\$49,300				х					\$49,300
x	Dehumidification	\$2,993,000				х	L				\$2,993,000
х	Control System Upgardes	\$90,400				х	L				\$90,400
	Electrical / LED Lighting										
х	Upgrade Lighting to LED (interior & exterior walls)	\$1,255,000				х					\$1,255,000
х	New Clocks only	\$47,900				Х	L		L		\$47,900
x	New PA Head End	\$20,500				х					\$20,500
х	New PA/Bell & Clock System	\$178,000				х					\$178,000
x	New Security Cameras (100)	\$164,400				х	L				\$164,400
х	Football Field LED fixtures/wiring	\$143,800				х	L				\$143,800
	Building Envelope Upgrades										
	Window Replacements	\$0				х					\$0
x	Priority 1	\$184,900				х					\$184,900
x	Priority 2	\$148,400				х					\$148,400
x	Priority 3	\$173,700				х					\$173,700
x	Replace Orig. Exterior Doors (1998)	\$238,800				х	L				\$238,800
	Tuckpointing (ARI report)	\$0				х	L				\$0
	Parking Lots & Sidewalks										
х	ADA sidewalks/paths to Home/Visitor bleachers	\$45,600				х					\$45,600
х	ADA ramp/stairs at door #9	\$130,800				Х					\$130,800
x	Pave rest of Bus Garage lot	\$119,600						х			\$119,600
x	Replace bus loop and drive	\$591,700						х			\$591,700
x	Replace path around Performing Arts	\$23,000				х					\$23,000
x	Patch/Seal/Sealcoat Play area	\$6,500				х	L				\$6,500
	Interior Finishes						L				
х	Older Carpet Replacements	\$114,000				х					\$114,000
x	Hallway Tile Replacement	\$249,700				х					\$249,700
x	Main Gym - Sand/Refinish/Lines	\$59,000				х					\$59,000
x	YMCA Gym - Sand/Refinish/Lines	\$43,100				х					\$43,100
	Other										
x	Replace Football Field Fencing	\$123,300				х					\$123,300
x	Playground ADA Engineered Wood Chips	\$98,600				х					\$98,600
	Performing Arts (Skydeck system)	\$532,500				х					\$532,500
x	Performing Arts (Misc. upgrades)	\$84,200	Ĺ	L		х	Ľ		Ĺ		\$84,200
	Irrigation System (TBD)	\$0	Ĺ			х	Ľ		Ĺ		\$0
	Track (TBD)	\$0				х					\$0
Т	New Bus Maintenance Shop (TBD)	\$0	Γ			х	Γ		Г	П	\$0


ISD#166 - PRELIMINARY BIM SUMMARY - DRAFT									
Project Selection Worksheet		1	tial Fu chani						
Building Improvement Measure (BIM) Description	Estimated Budget	Capital Health & Safety Safe Schools	LTFM Lease Levy	Abatement Energy Sayings	ESSER	"Selected Only" Estimated Budget			

COOK COUNTY SCHOOL ISD 166					
Mech. / Ventilation / IAQ Upgrades					
x Replace R-22 Cond. Unit/Coil for Performing Arts	\$71,200		x		\$71,200
x Replace R-22 Roof Top Units (2 - 1998 units)	\$102,700		x		\$102,700
Replace R-22 Roof Top Units (3 - 2008 units)	\$154,100		x		\$0
x Replace 2 - 2007 Domestic Hot Water Heaters	\$49,300		x		\$49,300
x Dehumidification	\$2,993,000		x		\$2,993,000
x Control System Upgardes	\$90,400		x		\$90,400




Utility Summary – Propane (includes YMCA)






Propane: \$






Utility Summary - Electricity







Electric: kWh \$






Utility Summary – Water & Sewer









Utility Summary









NEXT STEPS

- Continue to update budgets as new information is available
- Finish up Listening Session process
- Share Educational Adequacy and Listening Session Summary (Nov. 16th)
- Compare results of all assessments for common themes and overlap
- Begin the solutioning process



